

General Environmental Incident Summary

Incident: 3696 **Date/Time Notice:** 3/26/2015 **DEM Incident No:**
Responsible Party: Scott A. Williams
Date Incident: 3/26/2015 **Time Incident:** **Duration:**
County: McLean **Twp:** 144 **Rng:** 82 **Sec:** 13 **Qtr:**
Lat: 47.28748 **Long:** -101.01590 **Method:** Interpolation from map
Location Description: RDO Equipment Co.
1101 County Road 22
Washburn, ND 58577
Submitted By: Scott Williams **Affiliation:** Environmental Compliance Manag
Address: 3050 E Highway 95
City: Yuma **State:** AZ **Zip:** 85365

Received By:

Contact Person:

1101 County Road 22
Washburn, ND

Distance Nearest Occupied Building: 100 Feet **Release Contained:** Yes

Type of Incident: Phase II Environmental Boring

Description of Released Contaminant: Total Petroleum Hydrocarbons

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

During a Phase II Environmental Limited Site Investigation (2) bore sites reported a TPH of 3.3 ppm and 19.4 ppm. The second bore site also reported a 0.47 ppm of p-Isopropyltoluene.

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soil

Action Taken or Planned:

No immediate action was done or taken. This location is under remodel and a 100% self contained / recycle wash bay is being installed.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/26/2015 **Status:** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

Apparent petroleum contamination discovered during a site assessment. Followup is necessary. Report forwarded to Division of Water Quality, Groundwater Program.

Date: 4/1/2015 **Status:** Correspondence

Author: Suess, Bill

Updated Volume:

Notes:

I spoke with Scott Williams, the environmental compliance manager from RDO, and requested that he send me the Phase I and Phase II ESAs. After reviewing the reports, it was concluded that no significant hydrocarbon impacts are present at the site. No further action is warranted.